

COMPLIANT FUEL OIL NON-AVAILABILITY REPORT NORTH AMERICAN EMISSION CONTROL AREA (NA-ECA)

Name of vessel		Flag	IMO number					
SERIFOS		GREECE	9081837					
(If other relevant registration number is available, enter here)								
Provide a description of the vessel's voyage plan in place at the time of entry into the North American ECA (Attach copy of plan if availble)								
Vessel is presently sailing towards her next loading port St. John, after her previous								
discharge ops at Montreal. She has been fixed to perform a voy out of St John's with ETA there								
17th September. From her entrance at NAMERICA ECA on the 6th of Sep until now she has been								
using compliant bunkers of sulfur less than 1%. Re supply at Montreal was not possible due to tankage issues(vsl has only 2 bunkers tanks w/ 1 tank for HSFO 2nd tank part filled w/ LSFO)								
Last port of departure	Date of departure from last port (dd-mm-yyyy)							
Montreal	12 Sep 2013							
First port of arrival in Canada	Date of arrival at first Canadian port (dd-mm-yyyy)							
Montreal	10 Sep 2013							
Date vessel first received notice that it would be transiting in the NA-ECA (dd-mm-yyyy)								
Vsl already in ECA from previous voyage. Whilst in the ECA she was fixed to perform a v								
Vessel's location at the time of notice								
For her next voy she was already under discharge ops at Montreal and in compliance								
Date/time vessel operator expects to	Date/time vessel operator expects to exit NA-ECA (dd-mm-yyyy) (hh:mm UTC)							
already in ECA Zone, I	21 Sep 2013							
Projected days vessel's main propulsion engines will be in operation within								
15 days								
Sulphur content of fuel oil in use when entering and operating in the NA-ECA								
less than 1% until res	supply or if LSFO ROB is co	onsumed sh	e may need to :	switch to HSFO				
less than 1% until resupply or if LSFO ROB is consumed she may need to switch to HSFO Provide a description of actions taken to attempt to achieve compliance prior to entering NA-ECA, including a description of all attempts that were made to locate								
afternative sources of compliant fuel oil, and a description of the reason why compliant fuel oil was not available								
Currently rechecking with Bunker Brokers LQM is LSFO is available in St. John. However, prior								
advise provided on this particular port dictates no bunkers of any kind are available there. L								
Name of suppliers contacted	Address			Date of contact				
		***************************************		(dd-mm-yyyy)				
LQM	as brokers for possible supply at St. John			16/07/2013				
			······································					
		······						
in case of fuel oil supply disruption of	7.							
Name of port at which vessel was scheduled to receive compliant fuel oil								
St. john. previous experience dictates no bunkers available there.								
Name of the fuel oil supplier that was scheduled to deliver (and now reporting the non-availability)								
N/A								
17/5%								

65-0493E (1305-01) Page 1 of 2 Canadä^{*}

Operational constraints, if ap-						
Describe any operation const	traints that prevented using	g available compliant fue	el oil (e.g. with respect to viscosity or o	ther fuel oil parameters)		
N/A						
Specify steps you have taker	i, or are taking, to resolve t	these operational constr	aints that will allow you to use all com	mercially available residual fuel oil blends		
N/A						
Describe availability of compl	iant fuel oil at the first port	-of-call in Canada, and p	olans to obtain it			
Rechecking for bu	nker avails at S	St. John. in pr	evious port Montreal a	dditional LSFO was not		
possible due to t	ankage issues wh	nere we would h	ave to mix existing RO	B LSFO (currently vsl is		
using compliant L	SFO, since its ϵ	entrance to ECA	a) with new one.			
If compliant fuel oil is not a	vailable at the first port-of	-call in Canada, list the	lowest sulphur content of available	fuel oil(s) or the lowest sulphur content of		
available fuel oil at the next p			•	, , , , , , , , , , , , , , , , , , ,		
				list the number of Fuel Oil Non-Availabili		
		***************************************	while using non-compliant fuel oil as se	······		
Report	Date (dd-mm-yyyy)	Port	Type of fuel	Comments		
1	17-07-2013	St. Johns	HSFO			

Master name		1	Vessel operator name			
Tsekos Anastasios			Eletson Corporation			
Local agent in Canada			Vessel owner name			
TORMAR			Eletson Corporation			
Name of designated corporat	e official					
Zilakos Ioannis						
Address (street, city, country,	The state of the s			Telephone number		
Bunker Procuremen	t Officer 118 Ko	olokotroni Str	Piraeus Greece	210-459-8304		
	7//					
	<i>!</i>					
1//		Zilakos Ioann	is	16-09-2013		
Signature			Print name	Date (dd-mm-yyyy)		
// ///						
er carre vanne na						
85-0493E (1305-01) Page 2 of 2				Canad'ä		

Canadä